

BABA

RAJ ENGINEERS

ARCHITECTS, ENGINEERS, APPROVED VALUERS AND
27513404 STRUCTURAL ENGINEERS

Phone no. 9811129797

Office: H-34/35, 1st floor, Sector-3
Rohini, Delhi-110085

Residence: A-3/228, Sec-5, Rohini, Delhi-85

RAJ KUMAR

B.Sc., B.Tech(civil) I.I.T.Delhi, M-Tech (Structure)
Govt. Regd. Approved Valuer CAT - 1/396
Empanel SBI No. -CCO/CPM/VAL/99
MCD Regd License No. E-1025
MCD Regd Structural Engineer No. SE-21
Fellow Member of I.I.T.Arb. No. F- 0555
Life Member of I.B.C. Membership No. ML-6627
Member of C.I.A. Council.
Member of The Institution of Engineers (India)
Membership No. : M- 1578744

Date: 02/07/2018

SCHOOL HEALTH CERTIFICATE

- | | |
|--------------------------------------|--|
| 1. Name of the school | : VSPK INTERNATIONAL SCHOOL |
| 2. Location | : Sector- 13, Rohini, Delhi - 110085. |
| 3. Timing of school | : 8 AM to 3 PM |
| 4. No. of Staff | : Female -130, Male - 70, Total - 200 |
| 5. No. of students | : Female - 752, male -1070, Total - 1822. |
| 6. No. of Rooms | : 90. |
| 7. Arrangement of drinking water | : Delhi Jal Board.(With Filtered by R.O,& Water cooler) |
| 8. No. of Combined laterin for Girls | : 20. |
| 9. No. of Urinals for boys | : 22. |
| 10. No. of Laterines for boys | : 20, |
| 11. Sanitary condition | : Satisfactory. |


RAJ KUMAR

RAJ KUMAR
Architect & Engineers
Govt. Approved Valuer
M.C.D. Registration No. E-1025
H-34/35/3, 1st Floor, Sector-3,
Rohini Delhi-85, (M) 9811129797